



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program July 14, 2010

Reviewed: JAH

Mine Name: Lisbon Valley Mine	Permit Number: M037/0088
Operator Name: Lisbon Valley Mining Company LLC	Inspection Date: 06/22/2010
Inspector(s): T Munson	Time: 3PM
Other Participants: none	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Permit fees: current

Bond: n/a

Purpose of Inspection: To look at the revegetation of waste dump C.

Inspection Summary:

I was looking at Waste Dump C as I drove North on the county road and noticed that a portion of the West facing and South facing aspects of this dumps are poorly vegetated. My attached pictures show the areas in question. I subsequently had conversations with Lantz Indergard and he stated that the mine is proposing an expansion of waste Dump C to the South which would cover up this portion of the waste dump, hence the reason this area had not been worked on. Any other areas that are unvegetated on the West facing slopes will be drill seeded this fall.

Photos were taken to document site conditions.

Conclusions and Recommendations:

This issue of revegetation on Waste Dump C be revisited in the Fall of 2010 and an inspection and a meeting be held with the operator at this time.


Inspector's Signature T. Munson

TM:vs

cc:

BLM marie_mcgann@blm.gov
O:\M037-SanJuan\M0370088-LisbonValley-Summo\inspections\insp-062010.doc






South and West facing slopes



West Facing Slopes



Most of the area in this picture is poorly vegetated

